From: Jeffrey C Heffelman (Generation - 3) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP

(FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=JEFFRE3]

Sent: 5/13/2015 12:40:37 PM

To: Ed Baine (Generation - 3) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP

(FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Edwar62]; David Craymer (Generation - 34)

[/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=David09]

Subject: Fwd: Ash Pond ABC inspection 05/13/15 **Attachments**: 20150513091936491.pdf; ATT00001.htm

FYI

Sent from my iPhone

Begin forwarded message:

From: "Jeffrey R Marcell (Generation - 3)" < jeffrey.r.marcell@dom.com>

Date: May 13, 2015 at 11:42:36 AM EDT

To: "Michael J Winters (Generation - 34)" < Michael. J. Winters @dom.com >

Cc: "John Cima (Generation - 34)" < <u>john.cima@dom.com</u>>, "Jeffrey C Heffelman (Generation - 3)" < <u>Jeffrey.C.Heffelman@dom.com</u>>, "Kenneth Roller (Services - 6)" < <u>kenneth.roller@dom.com</u>>

Subject: RE: Ash Pond ABC inspection 05/13/15

Attached.

No Discharge at C Pond. Standing water around weir and Southeastern edge of Pond C and into center of C Pond beginning to recede. Water level inside bottom of weir is below pipe.

Very little to no seeping and dripping inside C Pond discharge weir about.

Standing water behind sand-bags at 'A' with standing water at the toe of the slope and flow under bags into rip-rap. The southern edge of the 'A' pond interior, from the SE corner to the sandbags, continues to hold water. The NE end of A Pond is holding water in pathway created from matting/equipment activity, noticeable depression in this section from activity related to drilling.

No standing water behind sand-bags at 'B' pond.

Precipitation on 05/11 was 0.19".

Let me know if you have any questions.

Jeff Marcell
Environmental Supervisor
Possum Point Power Station
Ladysmith & Remington CT Sites
703-441-3813 (phone)
8-795-3813 (tie)
703-441-3897 (fax)